

Asecos

Garanti: 12 ay
Bu ürüne ait Türkiye içi kapı teslim fiyat ve teslim süresi içeren teklifimizi almak için **info@yursat.com.tr** e-posta adresine başvuru yapabilir ya da ayrıntılı bilgi için +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaşabilirsiniz.
Asecos Markası, tedarik süresi için lütfen bizimle iletişime geçiniz.

Firmamız Asecos Türkiye Distribütörü veya temsilcisi değildir. Firmamız sipariş durumunda, belirtilen ürünlerde sadece Orjinal ve yeni ürün teklifi sunmaktadır. Bu sitede gösterilen Özel marka adları ve ticari markalar ilgili sahiplerinin mülkiyetindedir, talep durumunda kaldırılmaktadır.



Ürün	Açıklama
Artikel # 25099	Circulating air filter attachment for extracting Hydrocarbon vapors safety cabinets Installation outside the Ex zone Extraction from Ex zone 2 Filter: 3.5 kg activated carbon Potential-free alarm contact CE II 3 / - G Ex ic nA IIB T4 Gc
Ventilation attachment model HF.EA.8677.	14218 Ventilation attachment without exhaust air monitoring complete with connection cable and power plug The green control lamp goes out in the event of a power failure Connection spigot NW 75 W x D x H (mm): 200 x 400 x 200 ATEX-compliant: CE ExII 3 / - G Ex c IIC T4 Extraction from Ex-Zone 2 at Installation outside the Ex zone
S90.196.120.WDAS	
Asecos	
Asecos	
Asecos	
14220 HF.EA.11442	Ventilation attachment, with exhaust air monitoring
14218 HF.EA.8677	Ventilation attachment, with exhaust air monitoring

24212 HF.L.23746+	Filter activated carbon new filter (square) UFA.20.30+/*
14218	HF.EA.8677. - Ventilation attachment, without exhaust air monitoring
24212	HF.L.23746+ - Filter activated carbon new filter (square) UFA.20.30+/*
30115 001 33718	S-Class 90 S90-196-120
30115 002 30830	S-class90 S90-196-120
30612 001 30614	SL-Classic SL196 060MH
3022800133662	S-classic 90 S90 196-060-WDAS
Q.10171 C03	